

# BEECHCRAFT BONANZA/BARON

## Lower Cabin Door Reinforcement

**FAA / PMA Approved (STC SA01422AT-D)**

This STC is applicable to the Bonanza A36, A36TC/B36TC,  
V35B, F33A and 58 (Baron)

### Cabin door not latching or fitting as well as it used to? Experiencing air noise?

Check your lower cabin door hinge and see if it is loose. If the lower hinge on the cabin door is loose it typically means that cracks have developed around the lower cabin door hinge. These cracks result from the load imposed by passengers or wind attempting to open the door beyond its limits. If left unattended, this problem could lead to a major repair or replacement of the cabin door.

Summit Aviation Mfg has obtained a STC to modify the lower cabin door hinge area by incorporating a reinforcing stiffener. This modification will prevent the further propagation of cracks around the hinge area and protect the door from further damage.

